

Saline ground water, Spain

The Project:

Saline water pumping by means of vacuum systems, Spain

Executing company:

Fa. Ischebeck Iberica s.l.

Pol. INd. El Oliveral, Calle S, n 25

E-46190 Ribaroja del Turia

The Problem:

Extremely saline warm water (ground water contaminated by seawater) attacks conventional pumps of aluminium to a considerable extent which results in excessive wear which cannot be prevented by installing sacrificial anodes.

The Problem:

Extremely saline warm water (ground water contaminated by seawater) attacks conventional pumps of aluminium to a considerable extent which results in excessive wear which cannot be prevented by installing sacrificial anodes.



Specifikacije KTZ: <https://www.tsurumi.eu/sh-BA/ktz>

In the event of abrasive and corrosive utilization, stronger wear and tear will take place naturally in certain components. With regards to the above application wear and tear can take place mainly in impeller, agitator, suction plate, shaft sleeve, oil ring, mechanical seal, pump casing, strainer, motor casing and discharge coupling. Depending on the working conditions the lifetime of those parts might vary significantly and can be shorter than the legal warranty period.

In this regard, please pay attention to our [general terms and conditions](#) that we also send to you by mail on request.

